

Forestburgh Pond map note

Surface soils testing performed to check for lead left behind from a former shooting lane, indicated the presence of lead in the vicinity of lots 17 & 18. Further subsurface testing showed lead levels at 0-2 inches below ground and 12 – 16 inches below ground to be well below the Residential Use limits in NY State DEC guidelines. When drinking water wells are drilled on these lots, they should be tested for lead and water test results sent to Michael Kilmer , Environmental Engineer at the NY State DEC's Region 3 Office. Lead can easily be treated with a residential water filtration system